



Facilities Management Directorate

Log Date 20/05/10 16:10
PPM Group X - Unknown PPM Group

Job Number : 1062906

Help Desk Date : 20/05/10 Time : 16:10

Building	W005	Geoscience
Department	FM Directorate - Maintenance Services	
Recharge PN	B2320200	Logged By HELEN EASTMAN
Holding PN	Bld Mgr H Browning	6042
Account Code	5525	Planned Maintenance
Level	All	Room All Areas
Description	Estimate	Project/Work Approved
W005 GEOSCIENCE - PLEASE PROVIDE STRUCTURAL SURVEY OF AND REPORT ON CRACKING BRICKWORK AND SPALLING CONCRETE. REPORT TO INCLUDE PRICED RECOMMENDATIONS AND SUGGESTED PROGRAMME FOR REMEDIAL WORKS .		

Safety	Asbestos Information
Risk Assessment Carried Out By: <input type="text"/>	Asbestos Register Checked By: <input type="text"/>
Non Advised Although no specific information has been provided, staff must ensure that their working environment is safe	Working area/Room number not clearly defined by customer. Refer to Asbestos Register once location identified. Asbestos identified in building. Refer to Asbestos Register for details.
Testing	Contact & Access Details
Has the appropriate test certification been completed	8279

Electrical / Water Gas / Other

Comments

Approval given by HE to place an order with PBA to carry out Structural Assessment (11:06:10 TRC)

FeedBack

Help Desk	Mgmt 1	Mgmt 2	Mgmt 3	Project Ldr	Other Staff
VKS07TW	NPF	<input type="text"/>	<input type="text"/>	TRC	<input type="text"/>

Attended Date Time Completed Date Time

Actioned By (Please Print Name) PPM Ref